

propertyinspecting@gmail.com

www.CityPropertyInspections.com

Property Inspection Report Visual and Based on Access

THIRD PARTY USAGE FOR PURCHASE IS PROHIBITED AND ILLEGAL



Sample Report

Prepared Exclusively for: Client

Prepared by: Shawn S. Azimi Certified Master Inspector, or associates



Residentila-Condo or Townhouse.inspx

Table of Contents

Definitions	2
General Information	2
General Comments	3
Covered by Condo Association	3
Electrical	4
Structure	5
Air Conditioning	6
Fireplace/Wood Stove	7
Heating System	7
Plumbing	8
Bathroom	10
Kitchen	12
Bedroom	13
Living Space	15
Laundry Room/Area	15
Summary	16



Residentila-Condo or Townhouse.inspx

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the

time of inspection

Acceptable Functional, In generally good condition with no obvious signs of defect or

service or replacement need.

Needs Attention Marginal in condition and in the opinion of the inspector it should be monitored

from this point on for preventive care or regarding cost, liability or safety.

Serviceable Not fully or partially functional, hard to operate or unsafe in its present

condition. Inspector recommends further evaluation by an expert.

Not Inspected Not inspected because: Not within the scope of this inspection, was unsafe for

inspector, would damage property, not present, no utility on, No or limited

access or visibility or disconnected.

General Information

Property Information

Client Information

Inspection Company

Inspector Name Shawn Azimi

Company Name City Property Inspections

Conditions

Others Present Buyer, Buyer's Agent Property Occupied Occupied

Estimated Age 33Years Entrance Faces East

Start Time 3 PM End Time 5 PM

Electric On Yes

Gas/Oil On Yes

Water On Yes

Temperature 65 D

Weather Clear Soil Conditions Dry

Space Below Grade None

Building Type Condo Garage Detached

Water Source City How Verified

Sewage Disposal City How Verified

Additions/Modifications Unknown

Permits Obtained Unknown



Residentila-Condo or Townhouse.inspx

General Comments

- 1. General Comments By request of client, we inspected the subject property on Our findings regarding Functionality, Appearance, Condition, and Safety which cover the listed and itemized categories in this report are submitted herein. The following describe the the nature, scope and limitations of the this Report:
 - -A general inspection report based on visibility and accessibility of the components and sections of the subject property (Also, please see description of a general inspection in the signed Inspection agreement). We are not responsible for any third party complaints, dislikes, or claims, as this report is exclusively prepared for the client lis valid for the date of inspection, as changes due to, unknown and uncontrolled factors, construction before or after the inspection, disaster, or any sudden or hidden occurrences and progressive damages are NOT under our control, responsibility, or within scope of this inspection.
 - -It has been prepared by an independent property inspector, is unbiased in nature and is for the sole usage by our clients, unless otherwise authorized by them, to be reviewed (only) by others
 - -Cost estimates, if included, are by request of the client(s) named in this report, approximate, and provided as a matter of opinion and average market pricing
 - -It may only include sections and components in need of attention, service, or replacement as a brief reporting by client's request.
 - -Does not include any scientific, engineering, geological, or forensic data, opinion, or facts
 - -We ask and expect our client(s) to read the entire report, but for quick review and reference, summery pages are provided at the end of this report, and points of concern, attention, and service are printed in ink other than black within each section of the report. Summary pages do not include all the exiting condition.

Covered by Condo Association

Lots and Grounds: Unknown
 Exterior Surfaces: Unknown
 Roof: Unknown



Residentila-Condo or Townhouse.inspx

Electrical

1. Service Size Amps: 125 Volts: 120-240 VAC

2. Acceptable Service: Copper

3. Acceptable
4. Acceptable
5. Not Inspected
120 VAC Branch Circuits: Copper 240 VAC Branch Circuits: Copper Aluminum Wiring: Not Applicable

6. Acceptable Conductor Type: Non-metallic sheathed cable

7. Not Inspected Ground: No Access

8. Acceptable Smoke Detectors: See individual rooms

9. Acceptable Carbon Monoxide Detectors:

10. Not Inspected Security System: Not a part of this inspection

Left Side, Master bedroom Electric Panel -

11. Serviceable Manufacturer: Federal Pacific - Federal Pacific panel breakers have

a history of not tripping when circuit overloading occurs and some have caused fire. Recommend replacement due to background and history. Note: At the time of inspection no signs of arching, melting or other defects were visible to the naked eye. Consult a qualified

electrician for further evaluation.

12. Maximum Capacity: 125 Amps

13. Acceptable Main Breaker Size: None.

14. Serviceable Breakers: Copper - Non Original Brand Breakers: Breakers other

than the original manufacturer's used. It is recommended by electricians that the same type and brand be used to prevent aching

or other complications. Consult with a qualified electrician.








Residentila-Condo or Townhouse.inspx

Electrical (Continued)

Breakers: (continued)







15. Not Inspected Fuses: Not Applicable16. Not Inspected AFCI: Not Applicable

17. Acceptable GFCI: At GFCI receptacles only

18. Is the panel bonded? Yes

Structure

1. Acceptable Structure Type: Anchored Wood frame

2. Acceptable Foundation: Formed concrete

3. Not Inspected Differential Movement: Not Applicable

4. Not Inspected
5. Acceptable
6. Not Inspected
7. Not Inspected
8. Acceptable
9. Not Inspected
Stairs/Handrails: Not Applicable



Residentila-Condo or Townhouse.inspx

Structure (Continued)

10. Acceptable Subfloor: Plywood

Air Conditioning

In living room closet AC System -

1. Acceptable A/C System Operation: Functional at the time of inspection

2. Acceptable Condensate Removal: PVC

3. Acceptable Exterior Unit: Roof





Manufacturer: Ruud





5. Area Served: Interior Approximate Age: Fairly new

6. Fuel Type: 220 VAC Temperature Differential: 20

7. Type: Forced Air Capacity: 2 Ton

8. Acceptable Visible Coil: Copper / Aluminum coil with aluminum fins

9. Acceptable Refrigerant Lines: Low pressure and high pressure (Suction line and

liquid line)

10. Acceptable Electrical Disconnect: Pull type breaker at the unit

11. Not Inspected Exposed Ductwork: Not Visible.



Residentila-Condo or Townhouse.inspx

Air Conditioning (Continued)

12. Acceptable Blower Fan/Filters: Direct drive with filter

13. Acceptable Thermostats: Individual

Fireplace/Wood Stove

Since the Flue section (Heat and Smoke exhaust line) is not visible and requires snake camera inspection, is an specialty inspection and not part of this inspection, it is recommended that Flue be checked by a chimney expert for possible damage, misplacement, soot build up and need of cleaning.

Living Room Fireplace

1. Not Inspected Freestanding Stove: Not Applicable

2. Acceptable Fireplace Construction: Prefab

3. Type: Gas burning

4. Not Inspected Fireplace Insert: Not Applicable

5. Acceptable Smoke Chamber: Metal

6. Not Inspected Flue: Metal7. Acceptable Damper: Metal

8. Needs Attention Hearth: Flush mounted - Materials immediately adjacent to fire place

must be distinguishably non combustible: 16 to 20 inches at front and 6 to 10 inches at sides. This area is described as "Hearth" and must

be non combustible

Heating System

Living room closet Heating System

1. Acceptable Heating System Operation: Functional at Inspection time

2. Manufacturer: Ruud

3. Type: Forced air Capacity: 65000 BTUHR

4. Area Served: Interior Approximate Age: 5 to 10 Years.

5. Fuel Type: Electric

6. Acceptable Heat Exchanger:

7. Unable to Inspect: 50%

8. Acceptable Blower Fan/Filter: Direct drive with filter

9. Not Inspected Distribution: Not Visible

10. Acceptable Circulator: Fan

11. Acceptable Draft Control: Automatic12. Acceptable Flue Pipe: Not Applicable



Residentila-Condo or Townhouse.inspx

Heating System (Continued)

13. Acceptable Controls: Relief valve & Limit Switch14. Acceptable Devices: Pressure gauge + Temp gauge

15. Not Inspected
 16. Acceptable
 17. Not Inspected
 18. Humidifier: Not Applicable
 19. Thermostats: Individual
 19. Fuel Tank: Not Applicable

18. Tank Location: Not Applicable

19. Suspected Asbestos: No

Plumbing

1. Not Inspected Service Line: No Access

2. Not Inspected Main Water Shutoff: No Access

3. Not Inspected Water Lines: Copper for what is visible

4. Not Inspected
5. Not Inspected
6. Not Inspected
7. Not Inspected
Drain Pipes: ABS or Cast Iron
Vent Pipes: ABS or Cast Iron
Gas Service Lines: Rigid Steel

In closet add balcony Water Heater -

8. Acceptable Water Heater Operation: Functional at time of inspection







Residentila-Condo or Townhouse.inspx

Plumbing (Continued)

Water Heater Operation: (continued)





9. Manufacturer: American



10. Type: Natural gas Capacity: 40 Gal.

11. Approximate Age: Area Served: Interior

12. Acceptable Flue Pipe: Metal

13. Acceptable TPRV and Drain Tube: Copper



Residentila-Condo or Townhouse.inspx

Bathroom

#1, Right Side Bathroom

Closet: Single, Shared 1. Acceptable Ceiling: Paint and Paneling 2. Acceptable 3. Acceptable Walls: Paint and paneling

Floor: Tile 4. Acceptable Doors: Wood 5. Acceptable

6. Not Inspected Windows: Not Applicable

Electrical: 110 VAC GFCI or GFCI connected 7. Acceptable

Counter/Cabinet: Granite and Wood 8. Acceptable

9. Acceptable Sink/Basin: Porcelain coated 10. Acceptable Faucets/Traps: Metal and PVC

Tub/Surround: Fiberglass / fiberglass 11. Acceptable

12. Needs Attention Shower/Surround: Not Applicable - Diverter pullout knob is hard to

operate or not effective in directing water





- 13. Not Inspected
- Spa Tub/Surround: Not Applicable 14. Serviceable

Toilets: Toilet is loose. Secure as necessary, to prevent waste leakage.





Residentila-Condo or Townhouse.inspx

Bathroom (Continued)

15. Acceptable HVAC Source: Heat Registers16. Acceptable Ventilation: Electric ventilation fan

2, Left Side, Master Bathroom -

17. Acceptable
18. Acceptable
19. Acceptable
Walls: Paint and paneling

20. Acceptable Floor: Vinyl21. Acceptable Doors: Wood

22. Not Inspected Windows: Not Applicable

23. Acceptable Electrical: 110 VAC GFCI or GFCI connected

24. Acceptable Counter/Cabinet: Granite and Wood

25. Acceptable Sink/Basin: Porcelain coated26. Acceptable Faucets/Traps: Metal and PVC

27. Acceptable Tub/Surround:

28. Not Inspected Shower/Surround: Not Applicable 29. Not Inspected Spa Tub/Surround: Not Applicable

30. Serviceable Toilets: Toilet is loose. Secure as necessary, to prevent waste

leakage.



31. Acceptable HVAC Source: Heat Registers32. Acceptable Ventilation: Electric ventilation fan



Residentila-Condo or Townhouse.inspx

Kitchen

Left Side Kitchen

1. Needs Attention Cooking Appliances: Anti tip not installed or loose (Comes with the new units from manufacturer). Anti tip is an inexpensive bracket that holds the unit from tipping in case the front door is opened and weight is applied on it or a person (child) stands on the door. It secures the Oven Range to the wall or floor. This was tested simply by slightly pulling back on the unit. A safety notation



Acceptable Ventilator: Built In the Microwave

3. Acceptable Disposal:4. Acceptable Dishwasher:

5. Air Gap Present? Yes

6. Not Inspected Trash Compactor: Not Applicable

7. Not Inspected Refrigerator: Not a part of this inspection

8. Not Inspected Microwave: Not Applicable

9. Acceptable Sink: Stainless Steel

10. Serviceable Electrical: 110 VAC GFCI or GFCI connected - Faulty outlet with

loose, unconnected or crossed wires: Top of Counter





Residentila-Condo or Townhouse.inspx

Kitchen (Continued)

11. Acceptable Plumbing/Fixtures: Metal-PVC

12. Acceptable Counter Tops: Granite

13. Acceptable14. AcceptablePantry: Single

15. Acceptable Ceiling: Paint and Paneling16. Acceptable Walls: Paint and paneling

17. Needs Attention Floor: Hardwood - Surface scrathes, abrasion or wear out noted





18. Not Inspected Doors: Not Applicable19. Not Inspected Windows: Not Applicable

20. Acceptable HVAC Source: Heat Registers

Bedroom

#1, Right Side Bedroom

1. Acceptable Closet: Single

2. Acceptable Ceiling: Paint and Paneling3. Acceptable Walls: Paint and paneling

4. Acceptable5. AcceptableDoors: Wood



Residentila-Condo or Townhouse.inspx

Bedroom (Continued)

6. Needs Attention Windows: Aluminum Slider - Semi hard operation. Repair / Lubricate as necessary.



7. Acceptable Electrical: 110 VAC

8. Acceptable9. AcceptableWAC Source: Heat RegistersSmoke Detector: Hard wired

2, Left Side, Master Bedroom -

10. Acceptable Closet: Single

11. Acceptable Ceiling: Paint and Paneling12. Acceptable Walls: Paint and paneling

13. Acceptable14. AcceptableDoors: Wood

15. Acceptable Windows: Aluminum Slider

16. Acceptable Electrical: 110 VAC

17. Acceptable18. Acceptable17. Acceptable18. Acceptable18. Acceptable19. Acceptable



Residentila-Condo or Townhouse.inspx

Living Space

Living Room Living Space

1. Acceptable Closet: Double

2. Acceptable Ceiling: Paint and Paneling3. Acceptable Walls: Paint and paneling

Acceptable Floor: Hardwood

5. Acceptable Doors: Wood, Also, entry door6. Acceptable Windows: Aluminum Slider

7. Acceptable Electrical: 110 VAC

8. Acceptable HVAC Source: Heat Registers9. Not Inspected Smoke Detector: Not Applicable

Laundry Room/Area

Hallway to the right side bathroom Laundry Room/Area

Not Inspected Closet: Not Applicable
 Acceptable Ceiling: Paint and Paneling
 Acceptable Walls: Paint and paneling

4. Acceptable Floor:

5. Acceptable Doors: Wood

6. Not Inspected Windows: Not Applicable

7. Acceptable Electrical: 110 VAC

8. Not Inspected
9. Not Inspected
10. Not Inspec

11. Not Inspected Laundry Tub Drain: Not Applicable

12. Not Inspected Washer Hose Bib: Not visible

13. Acceptable Washer and Dryer Electrical: 110 VAC

14. Not Inspected Dryer Vent: Access Limited15. Not Inspected Dryer Gas Line: Not Visible

16. Not Inspected Washer Drain: Wall mounted drain

17. Not Inspected Floor Drain: Not visible



Residentila-Condo or Townhouse.inspx

Needs Attention Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Fireplace/Wood Stove

- Living Room Fireplace Hearth: Flush mounted Materials immediately adjacent to fire place must be distinguishably non combustible: 16 to 20 inches at front and 6 to 10 inches at sides. This area is described as "Hearth" and must be non combustible Bathroom
- # 1, Right Side Bathroom Shower/Surround: Not Applicable Diverter pullout knob is hard to operate or not effective in directing water Kitchen
- 3. Left Side Kitchen Cooking Appliances: Anti tip not installed or loose (Comes with the new units from manufacturer). Anti tip is an inexpensive bracket that holds the unit from tipping in case the front door is opened and weight is applied on it or a person (child) stands on the door. It secures the Oven Range to the wall or floor. This was tested simply by slightly pulling back on the unit. A safety notation
- 4. Left Side Kitchen Floor: Hardwood Surface scrathes, abrasion or wear out noted Bedroom
- 5. # 1, Right Side Bedroom Windows: Aluminum Slider Semi hard operation. Repair / Lubricate as necessary.



Residentila-Condo or Townhouse.inspx

Serviceable Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Electrical

- 1. Left Side, Master bedroom Electric Panel Manufacturer: Federal Pacific Federal Pacific panel breakers have a history of not tripping when circuit overloading occurs and some have caused fire. Recommend replacement due to background and history. Note: At the time of inspection no signs of arching, melting or other defects were visible to the naked eye. Consult a qualified electrician for further evaluation.
- 2. Left Side, Master bedroom Electric Panel Breakers: Copper Non Original Brand Breakers: Breakers other than the original manufacturer's used. It is recommended by electricians that the same type and brand be used to prevent aching or other complications. Consult with a qualified electrician.

Bathroom

- 3. # 1, Right Side Bathroom Toilets: Toilet is loose. Secure as necessary, to prevent waste leakage.
- 4. # 2, Left Side, Master Bathroom Toilets: Toilet is loose. Secure as necessary, to prevent waste leakage.

Kitchen

5. Left Side Kitchen Electrical: 110 VAC GFCI or GFCI connected - Faulty outlet with loose, unconnected or crossed wires: Top of Counter