

propertyinspecting@gmail.com

www.CityPropertyInspections.com

Property Inspection Report Visual and Based on Access

THIRD PARTY USAGE FOR PURCHASE IS PROHIBITED AND ILLEGAL



MunIti Unit-Income Property

Prepared Exclusively for: Client

Prepared by: Shawn S. Azimi Certified Master Inspector, or associates



Multi Unit-Sample Report.inspx

Table of Contents

Definitions	3
General Information	3
General Comments	4
Lots and Grounds	5
Exterior	8
Structure	12
Roof	14
Electrical	17
Plumbing	18
Air Conditioning	23
Heating System	23
Laundry Room/Area	24
Unit #1	24
Unit #2	28
Unit #3	33
Unit #4	38
Unit #5	43
Unit #6	47
Unit #7	52
Unit #8	58
Unit #9	62



Multi Unit-Sample Report.inspx

Table of Contents (continued)

Unit #10	66
Unit #11	69
Unit #12	72
Unit #13	72
Unit #14	75
Unit #15	76
Unit #16	79
Unit #17	81
Unit #18	84
Unit #19	87
Unit #20	88
Summary	93



Multi Unit-Sample Report.inspx

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the

time of inspection

Not Inspected

Acceptable Functional, In generally good condition with no obvious signs of defect or

service or replacement need.

Needs Attention Marginal in condition and in the opinion of the inspector it should be monitored

from this point on for preventive care or regarding cost, liability or safety.

Serviceable Not fully or partially functional, hard to operate or unsafe in its present

condition. Inspector recommends further evaluation by an expert.

Not inspected because: Not within the scope of this inspection, was unsafe for inspector, would damage property, not present, no utility on, No or limited

access or visibility or disconnected.

General Information

Property Information

City State CA Zip

Client Information

Inspection Company

Inspector Name Shawn Azimi

Company Name City Property Inspections

Address City Property Services

Phone 818 687 8686

E-Mail Propertyinspecting@gmail.com

Conditions

Others Present Buyer's Agent Property Occupied Partially occupied

Estimated Age Unknown Entrance Faces West

Start Time 10 AM End Time 3 PM

Electric On Yes

Gas/Oil On Yes

Water On Yes

Temperature 79F

Weather Clear Soil Conditions Dry

Building Type Multi Unit Income Property Garage Sub garage



Multi Unit-Sample Report.inspx

General Information (Continued)

Sewage Disposal City How Verified Water Source City How Verified Additions/Modifications Unknown Permits Obtained Unknown

General Comments

- 1. General Comments By request of client......, we inspected the subject property on Our findings regarding Functionality, Appearance, Condition, and Safety which cover the listed and itemized categories in this report are submitted herein. The following describe the the nature, scope and limitations of the this Report:
 - -A general inspection report based on visibility and accessibility of the components and sections of the subject property (Also, please see description of a general inspection in the signed Inspection agreement) We are not responsible for any third party complaints, dislikes, or claims., as this report is exclusively prepared for the client
 - -It is valid for the date of inspection, as changes due to, unknown and uncontrolled factors, construction before or after the inspection, disaster, or any sudden or hidden occurrences and progressive damages are NOT under our control, responsibility, or within scope of this inspection
 - -It has been prepared by an independent property inspector, is unbiased in nature and is for the sole usage by our clients, unless otherwise authorized by them
 - -Cost estimates, if included, are by request of the client(s) named in this report, approximate, and provided as a matter of opinion and average market pricing
 - -It may only include sections and components in need of attention, service, or replacement as a brief reporting by client's request.
 - -Does not include any scientific, engineering, geological, or forensic data, opinion, or facts
 - -We ask and expect our client(s) to read the entire report, but for quick review and reference, summery pages are provided at the end of this report, and points of concern, attention, and service are printed in ink other than black within each section of the report. Summary pages do not include all the exiting condition.



Multi Unit-Sample Report.inspx

Lots and Grounds

1. Needs Attention Walkways: Safety Notation: Any area or spot with level or grade differential, projected objects from ground, openings on walk path and notable unevenness inside or outside the property should be repaired or improved to prevent trip and injury hazard. If improvement is not desired or not possible, use with caution and use night lighting. Photos could be sample representative, as all areas may not have been visible or accessible to the inspector.





2. Acceptable

3. Acceptable

4. Not Inspected

Walkway Drainage: Slope Drain Steps/Stairs: Concrete, Wood Vegetation: Not Applicable

5. Needs Attention Retaining Walls: Minor cracks and separation noted. Monitor and maintain.







Multi Unit-Sample Report.inspx

Lots and Grounds (Continued)

Retaining Walls: (continued)



- 6. Acceptable
- 7. Acceptable

Grading:

Driveway: Concrete - Cracks commonly seen, noted.



8. Serviceable

Fences: Fence at right side (protective barrier for pool deck) is aged and due for replcement.



9. Not Inspected

Lawn Sprinklers:




Multi Unit-Sample Report.inspx

Lots and Grounds (Continued)

10. Needs Attention Parking Lot: Monitor and maintain per following reasons:

1. Crack on floor without displacement, 2. Moisture affects, efflorescence (salty residue due to moisture seepage) on concrete





Multi Unit-Sample Report.inspx

Lots and Grounds (Continued)

Parking Lot: (continued)



11. Acceptable

Parking Lot Lighting:

12. Acceptable

Parking Lot Drainage: Slope Drain

13. Access ADA Compliant: No

Exterior

Exterior Surface -

 Needs Attention Type: Stucco - 1.Any opening, separation, or crack on the exterior walls should be sealed patched and painted as necessary, to prevent further decay and admittance of water, insect or rodent traffic, 2.
 Entire exterior is due for resurfacing and paint coating







Multi Unit-Sample Report.inspx

Exterior (Continued)

Type: (continued)





Multi Unit-Sample Report.inspx

Exterior (Continued)

Type: (continued)



2. Acceptable Main Entry:

3. Main Entry Access ADA Compliant: No

4. Not Inspected Secondary/Other Entry:

5. Secondary/Other Entry Access ADA Compliant: Not applicable

6. Not Inspected Rear Entry: Not Applicable

7. Serviceable Trim: Wood - Due for repair and painting.

8. Serviceable Fascia: Wood - Due for repair and painting.





Multi Unit-Sample Report.inspx

Exterior (Continued)

Fascia: (continued)



9. Acceptable

Soffits:

10. Acceptable

Patio Door: Metal sliding

11. Needs Attention Windows: Some of the window security bars are not equipped with

release mechanism from inside, for emergency existing.





12. Serviceable

Exterior Lighting: Exposed wiring at different areas noted. Cover and secure as possible. Consult an electrician.







Multi Unit-Sample Report.inspx

Exterior (Continued)

Exterior Lighting: (continued)





13. Not Inspected Exterior Electric Outlets: Not Applicable

14. Acceptable Canopy: Wood and Stucco

15. Acceptable Type:16. Acceptable Roof:17. Acceptable Structure:

Structure

1. Acceptable Structure Type: Anchored Wood Framing

2. Acceptable Foundation: Formed Concrete

3. Not Inspected Differential Movement: Not Applicable

4. Acceptable Beams: Metal and Wood

5. Needs Attention Bearing Walls: Minor cracks noted. Monitor and maintain.





6. Not Inspected7. Not Inspected8. Acceptable

Joists/Trusses: Not Visible Piers/Posts: Not Applicable Floor/Slab: Wood / Concrete




Multi Unit-Sample Report.inspx

Structure (Continued)

9. Serviceable

Stairs/Handrails: 1. Safety hazard with sharp top, 2. Short for protection, 3. Openings / Spacing at Balusters / Frame bars: Too far apart. Child and pet safety. Recommend installing more obstruction for safety.



10. Not Inspected S

Subfloor: Plywood




Multi Unit-Sample Report.inspx

Roof

Main Structure Roof Surface

1. Method of Inspection: On roof





- Not Inspected
- 3. Serviceable

Unable to Inspect: Not Applicable

Material: 1.Minor sporadic repair / patching needed at present, 2. Water ponding stains evident. Monitor and maintain, 3. Roof material has been covered with gravel at a few areas that show sagging. This is an improper way of draining water, and moisture entrapment under the gravel will reduce the life expectancy of the area covered, 4. Per notations in 3, the sagging of the roof deck must be corrected as a long term remedy for proper draining, as this roof is not equipped with scupper system and it is slope draining system. Consult a roofer.







Multi Unit-Sample Report.inspx

Roof (Continued)

Material: (continued)



4. Serviceable

Flashing: Water pregnable





5. Not Inspected

6. Not Inspected

Valleys: Not Applicable Skylights: Not Applicable

7. Needs Attention Plumbing Vents: 1. Many are due for replacement, 2. Some are









Multi Unit-Sample Report.inspx

Roof (Continued)

Plumbing Vents: (continued)



8. Acceptable

Roof Drains: Slope Drain - From left to right and with uneven roof

deck, mostly at front

9. Serviceable

Gutters: Gutters should be corrected in pitch, not to become stuffed.





10. Acceptable

Downspouts:

11. Acceptable Chimney ——

Leader/Extension:

12. Not Inspected

Chimney: Not Applicable

13. Not Inspected

Flue/Flue Cap: Not Applicable

14. Not Inspected

Chimney Flashing: Not Applicable



Multi Unit-Sample Report.inspx

Electrical

1. Serviceable Electrical System: Due to all notations below and other deficiencies,

such 2 socket and Non GFCI, age of system, possible lack of safety and proper grounding and exposed wiring, total revitalization of the electrical system, for safety and liability reasons, is recommended.

2. Service Size Amps: 200 Double Fuse System Volts: 110-240 VAC

3. Acceptable Service: Copper

4. Acceptable 120 VAC Branch Circuits: Copper - Cloth Wiring Insulation: Circuit

branches of a property this aged, may be covered by cloth insulators,

which are outdated and may not be safe by today's standards.

Intrusive discovery is not a part of this inspection and to verify if the

said substance is present, consult with a qualified electrician.

5. Acceptable6. Not Inspected240 VAC Branch Circuits: Copper Aluminum Wiring: Not Applicable

7. Acceptable Conductor Type: Non-metallic sheathed cable

8. Acceptable Ground: No Access

Left Side Electric Panel -

9. Serviceable Manufacturer: Federal Pacific - 1. Federal Pacific panel breakers, with

"Stab Lock" design have a history of not tripping when circuit overloading occurs. Consult a qualified electrician to verify if

replacement is needed, 2.

10. Maximum Capacity: 400 Amp

11. Acceptable Main Breaker Size: 400 Amp

12. Acceptable
13. Acceptable
14. Not Inspected
15. Not Inspected
16. Specification
17. Breakers: Copper Fuses: Bullet Type AFCI: Not Applicable GFCI: Not Applicable GFCI: Not Applicable

16. Is the panel bonded? No

17. Not Inspected Smoke Detectors: Not Applicable

18. Not Inspected Data/Security Systems: Not Applicable

19. Serviceable Emergency Lighting: Not installed. Consult an electrician.



Multi Unit-Sample Report.inspx

Plumbing

1. Acceptable







2. Serviceable

Water Lines: 1.At rear: Between pool rear retaining wall and front units rear parameter walls-, A. One or more copper-galvanized connections are of improper fitting material which may cause "Dielectric" or Galvanic / Electrolysis, leading to rupture. Consult a plumber for remedy and cost, B. Corrosion on galvanized pipe can cause rupture at any time 2. In Sub Garage: Swere and other drain lines show corrosion, and past leakage signs, which are susceptible to leakage at any time. Recommend repair / replacement by a professional plumber, to prevent damaged on vehicles parked underside the said pipes, as well as health and sanitation issues. Some temporary repairs by felt rapping noted.





Multi Unit-Sample Report.inspx


Plumbing (Continued)

Water Lines: (continued)



3. Serviceable

Drain Pipes: See above notes.





Multi Unit-Sample Report.inspx

Plumbing (Continued)

Drain Pipes: (continued)





4. Acceptable

Service Caps:



Utility room and Mall space (between pool deck and rear units) Water Heater



Multi Unit-Sample Report.inspx

Plumbing (Continued)

5. Serviceable

Water Heater Operation: Functional at time of inspection - Some routine maintenance on boiler and reserve tank are needed. Consult a plumber.











Multi Unit-Sample Report.inspx

Plumbing (Continued)

Water Heater Operation: (continued)





6. Type: Natural gas Capacity: 100 Gal., 40 Gal.

7. Approximate Age: 15 to 20 Years Area Served: Interior



Multi Unit-Sample Report.inspx

Plumbing (Continued)

8. Acceptable

Flue Pipe:



9. Acceptable

TPRV and Drain Tube:

Air Conditioning

Not Installed AC System -

1. Not Inspected Exposed Ductwork:

2. Not Inspected Blower Fan/Filters:

3. Not Inspected Thermostats:

Heating System

Wall Units- Some not Functional Heating System -

1. Serviceable Thermostats: Some of the thermostats and Wall units are not functional.

- 2. Not Inspected
- 3. Not Inspected



Multi Unit-Sample Report.inspx

Laundry Room/Area

At right side of the sub garage Laundry Room/Area

1. Not Inspected Closet: Not Applicable

2. Acceptable Ceiling:3. Acceptable Walls:4. Acceptable Floor:

5. Not Inspected Doors: Not Applicable6. Not Inspected Windows: Not Applicable

7. Acceptable Electrical:

8. Not Inspected
9. Not Inspected
10. Not Inspec

11. Not Inspected Laundry Tub Drain: Not Applicable

12. Acceptable Washer Hose Bib:

13. Acceptable Washer and Dryer Electrical:

14. Acceptable Dryer Vent:15. Acceptable Dryer Gas Line:

16. Acceptable Washer Drain: Wall mounted drain

17. Not Inspected Floor Drain:

Unit #1

- 1. Unit #: 12, 1st Floor Unit Type:
- 2. Occupied

Interior Rooms

Living Room Living Space -

3. Closet: None

4. Acceptable Ceiling: Paint and Paneling5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate 7. Acceptable Doors: Wood

8. Needs Attention Windows: Aluminum Fixed - Not Tempered glasses

9. Acceptable Electrical: 110 VAC

10. Not Inspected HVAC Source: Not Applicable

11. Not Inspected



Multi Unit-Sample Report.inspx

Unit #1 (Continued)

Kitchen

Open to Living Room Kitchen -

12. Acceptable Cooking Appliances: Hotpoint

13. Acceptable Ventilator: Window14. Acceptable Disposal: Badger

15. Needs Attention Dishwasher: SPT - Needs to fit in right.



16. Air Gap Present? Yes

17. Not Inspected Trash Compactor:

18. Not Inspected Refrigerator:19. Not Inspected Microwave:

20. Acceptable Sink: Stainless Steel

21. Serviceable Electrical: Non GFCI outlet





Multi Unit-Sample Report.inspx

Unit #1 (Continued)

22. Not Inspected Plumbing/Fixtures: Not inspected because of obstruction.



23. Acceptable Counter Tops: Formica

24. Acceptable Cabinets: Wood25. Not Inspected Pantry: None

26. Acceptable Ceiling: Paint and Paneling27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors: Not Applicable30. Acceptable Windows: Aluminum slider

31. Not Inspected HVAC Source: No HVAC source

Hallwavs

32. Acceptable Ceiling: Paint and Paneling

33. Not Inspected Closet: None 34. Acceptable Floor: Laminate

35. Not Inspected

36. Not Inspected Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Hall Way Bathroom -

38. Not Inspected Closet: None

39. Acceptable Ceiling: Paint and Paneling 40. Acceptable Walls: Paint and paneling

41. Acceptable
42. Acceptable
43. Not Inspected
Floor: Laminate
Doors: Wood
Windows: None



Multi Unit-Sample Report.inspx

Unit #1 (Continued)

44. Serviceable

Electrical: Non GFCI outlet



45. Acceptable

46. Acceptable

47. Not Inspected

Counter/Cabinet: Granite and Wood.

Sink/Basin: Porcelain coated Faucets/Traps: Not visible



48. Not Inspected

49. Acceptable

50. Not Inspected 51. Acceptable

52. Not Inspected

53. Acceptable

Tub/Surround:

Shower/Surround: Tile and Tile, Glass

Spa Tub/Surround:

Toilets: American Standard

HVAC Source:

Ventilation: Electric ventilation fan

Bedrooms

Rear Bedroom -



Multi Unit-Sample Report.inspx

Unit #1 (Continued)

54. Needs Attention Closet: Large - Closet door needs repair. Tracks / Guides / Wheels are missing or not functional.



55. Acceptable Ceiling: Paint and Paneling56. Acceptable Walls: Paint and paneling

57. Acceptable Floor: Laminate 58. Acceptable Doors: Wood

59. Acceptable Windows: Aluminum Fixed,, Aluminum slider

60. Acceptable Electrical: 110 VAC 61. Not Inspected HVAC Source:

62. Not Inspected

Balcony

63. Not Inspected Balcony Floors:

Unit #2

- 1. Unit #: 14 Unit Type: SINGLE CONDO
- 2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable Closet: Large



Multi Unit-Sample Report.inspx

Unit #2 (Continued)

4. Serviceable

Ceiling: Paint and Paneling - Evidence of past or present water staining. Invasive inspection will reveal plumbing leakage or roof water pregnable points.



5. Serviceable

Walls: Paint and paneling - Evidence of past or present water damage noted. To determine the existence or activity of mold, inspection by mold expert is required.





6. Acceptable

Floor: Laminate

7. Acceptable

Doors: Wood, Also entry

8. Acceptable

Windows: Jalousie

9. Acceptable

Electrical: 110 VAC

10. Acceptable

HVAC Source: Wall Unit

11. Not Inspected

Smoke Detector: Not a part of this inspection

Kitchen

Open to Living Room Kitchen



Multi Unit-Sample Report.inspx

Unit #2 (Continued)

12. Serviceable

Cooking Appliances: No anti tip is installed (Comes with the new unit from manufacturer). Anti tip is a bracket that holds the unit from tipping in case the front door is opened and weight is applied on it or a person (child) stands on the door. It secures the Oven Range to the wall or floor. This was tested simply by pulling back on the unit. A safety notation.



13. Serviceable





14. Serviceable

<u>Disposal: In-Sinkerator - Inoperative</u>





Multi Unit-Sample Report.inspx

Unit #2 (Continued)

15. Not Inspected Dishwasher: Not applicable

16. Air Gap Present? No

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable

20. Acceptable Sink: Stainless Steel

21. Serviceable Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled

outlet. Consult a qualified Electrician.



22. Acceptable Plumbing/Fixtures: PVC, Chrome


23. Acceptable Counter Tops: Formica

24. Acceptable Cabinets: Wood25. Acceptable Pantry: Small

26. Acceptable Ceiling: Paint and Paneling

27. Serviceable Walls: Paint and paneling - Evidence of past or present water damage noted. To determine the existence or activity of mold,

inspection by mold expert is required.



28. Acceptable Floor: Laminate



Multi Unit-Sample Report.inspx

Unit #2 (Continued)

29. Not Inspected Doors: Not applicable

30. Acceptable Windows: Aluminum crank31. Not Inspected HVAC Source: Not applicable

Hallways

Bathrooms

Left side, Rear Bathroom

32. Not Inspected Closet: Not applicable

33. Acceptable Ceiling: Paint and Paneling

34. Serviceable Walls: Paint and paneling - Evidence of past or present water

damage noted. To determine the existence or activity of mold,

inspection by mold expert is required.



35. Acceptable Floor: Tile 36. Acceptable Doors: Wood

37. Not Inspected Windows: Not applicable38. Acceptable Electrical: 110 VAC GFCI

39. Acceptable Counter/Cabinet: Composite and wood 40. Acceptable Sink/Basin: One piece sink/counter top

41. Acceptable Faucets/Traps: Metal / PVC42. Not Inspected Tub/Surround: Not applicable

43. Acceptable Shower/Surround: Fiberglass pan and fiberglass surround

44. Not Inspected Spa Tub/Surround: Not applicable

45. Acceptable Toilets:

46. Not Inspected HVAC Source: Not applicable 47. Acceptable Ventilation: Electric ventilation fan

Bedrooms



Multi Unit-Sample Report.inspx

Unit #2 (Continued)

Bedroom

Balcony

Unit #3

- 1. Unit #: Unit 18, First floor Unit Type: 1 bedroom
- 2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable4. AcceptableCloset: NoneCeiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable
8. Acceptable
9. Acceptable
Doors: Aluminum Slider
Windows: Aluminum Fixed
Electrical: not in service

10. Acceptable HVAC Source: Wall Unit, Wall heater.

11. Not Inspected Smoke Detector: Not Applicable

Kitchen

Right side rear Kitchen

12. Acceptable Cooking Appliances: Amana

13. Serviceable Ventilator: No Vent - Microwave in operative.



14. Acceptable Dispo15. Acceptable Dishw

Disposal: In-Sinkerator Dishwasher: Not applicable



Multi Unit-Sample Report.inspx

Unit #3 (Continued)

16. Air Gap Present? No

17. Acceptable Trash Compactor: None18. Acceptable Refrigerator: Magic chef

19. Serviceable Microwave: No name - Inoperative



20. Acceptable21. Serviceable

Sink: Stainless Steel

Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled

outlet. Consult a qualified Electrician. One or more.



22. Acceptable Plumbing/Fixtures: Chrome /Brass

23. Acceptable Counter Tops: Formica

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Single small
Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate 29. Acceptable Doors: None

30. Acceptable Windows: Aluminum slider31. Acceptable HVAC Source: Wall Unit



Multi Unit-Sample Report.inspx

Unit #3 (Continued)

Hallways

32. Acceptable Ceiling: Paint and Paneling

33. Acceptable Closet: Double slider

34. Acceptable Floor: Laminate35. Smoke Detector: Not Applicable

36. Serviceable Thermostat: Inoperative,









37. Acceptable

Bathrooms

Walls: Paint and paneling

Front left Bathroom -

38. Acceptable Closet: None

39. Acceptable Ceiling: Paint and Paneling



Multi Unit-Sample Report.inspx

Unit #3 (Continued)

40. Acceptable

Walls: Paint and paneling - Past repairs



41. Acceptable

42. Acceptable

43. Acceptable

44. Serviceable

Floor: Laminate Doors: Wood Windows: None

Electrical: 110 VAC - Non-GFCI or GFCI labeled outlet. Consult a

qualified Electrician. One or more.



45. Acceptable

46. Acceptable

47. Acceptable

48. Serviceable

Counter/Cabinet: Tile and Wood Sink/Basin: Porcelain coated Faucets/Traps: Metal / Metal

Tub/Surround: Porcelain tub and ceramic tile surround - Cracked

tiles. One or more.



Multi Unit-Sample Report.inspx

Unit #3 (Continued)

Tub/Surround: (continued)





49. Acceptable

Shower/Surround: Tile and Tile

50. Acceptable

Spa Tub/Surround: None

51. Acceptable

Toilets: American Standard HVAC Source: None

52. Acceptable

Verilla de Electrica es dis

53. Acceptable

Ventilation: Electric ventilation fan

Bedrooms

Rear Bedroom

54. Acceptable Closet: Double slider

55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable58. AcceptableDoors: Wood

59. Serviceable Windows: Aluminum slider - Handle missing.





Multi Unit-Sample Report.inspx

Unit #3 (Continued)

60. Acceptable Electrical: 110 VAC 61. Acceptable HVAC Source: None

62. Acceptable Smoke Detector: Inoperative or missing. Inoperative, or missing. One

or more.

Balcony

63. Serviceable Balcony Floors: Concrete. Monitor and maintain. Negative ptich and

water ponding.



64. Acceptable Balcony Ceilings: Stucco Balcony Walls: stucco

66. Acceptable Balcony Electrical & Safety Railings: none

Unit #4

1. Unit #: #19, first floor Unit Type: Single

2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable Closet: None



Multi Unit-Sample Report.inspx

Unit #4 (Continued)

4. Serviceable Ceiling: Popcorn - Water stains noted. Holes for water release noted. Invasive inspection may reveal possible mold presence.





5. Serviceable

Walls: Paint and paneling - Loose or peeling paint.





6. Serviceable

Floor: Laminate - Floor; stained.



7. Acceptable

8. Acceptable Windows: Aluminum Crank

9. Serviceable

Electrical: not in service - Not in service.

10. Acceptable

HVAC Source: Wall Unit



Multi Unit-Sample Report.inspx

Unit #4 (Continued)

11. Serviceable Smoke Detector: Inoperative or missing. Inoperative, or missing. One

or more.

Kitchen

left rear Kitchen -

12. Acceptable Cooking Appliances: Premier

13. Acceptable Ventilator: Fan to Shaft

14. Acceptable Disposal: None15. Acceptable Dishwasher: None

16. Air Gap Present? No

17. Acceptable18. Acceptable19. Acceptable

19. Acceptable Microwave: Danby20. Acceptable Sink: Porcelain Coated

21. Not Inspected Electrical: Not in service - Power off

22. Serviceable Plumbing/Fixtures: Chrome /Brass - Water leakage.



23. Acceptable

24. Serviceable

Counter Tops: Formica

Cabinets: Wood - No drawer stops. One or more





Multi Unit-Sample Report.inspx

Unit #4 (Continued)

25. Acceptable
26. Acceptable
27. Acceptable
Walls: Paint and paneling

28. Acceptable Floor: Laminate29. Acceptable Doors: None

30. Acceptable Windows: Aluminum Crank

31. Acceptable HVAC Source: None

Hallways

32. Serviceable Ceiling: Popcorn - Stress cracks



33. Acceptable

34. Acceptable

35. Not Inspected

36. Serviceable

Closet: Double slider, Shelves above

Floor: Laminate

Smoke Detector: Inoperative or missing. Not a part of this inspection.

Thermostat: Inoperative



37. Acceptable

Bathrooms

Walls: Paint and paneling



Multi Unit-Sample Report.inspx

Unit #4 (Continued)

left side center Bathroom -

38. Acceptable

Closet: None

39. Acceptable

Ceiling: Paint and Paneling - Cracks present. Not Structural or

Mechanical.



40. Acceptable

Walls: Paint and paneling - Evidence of past repair or damage



41. Acceptable

42. Acceptable 43. Acceptable

44. Serviceable 45. Serviceable

Doors: Wood Windows: None

Electrical: 110 VAC - Power off

Counter/Cabinet: Tile and Wood - Sliding door; Will not open. One

or more.



Multi Unit-Sample Report.inspx

Unit #4 (Continued)

Counter/Cabinet: (continued)



46. Acceptable Sink/Basin: Porcelain coated 47. Acceptable Faucets/Traps: Metal / Metal

48. Acceptable Tub/Surround: Porcelain tub and ceramic tile surround

49. Acceptable Shower/Surround:

50. Acceptable Spa Tub/Surround: None

51. Acceptable Toilets: Koehler

52. Acceptable HVAC Source: None

53. Acceptable Ventilation: Electric ventilation fan

Bedrooms

Bedroom ·

Balcony

Unit #5

- 1. Unit #: 17,1st Floor Unit Type:
- 2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable Closet: Large4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable Doors: aluminum, Wood



Multi Unit-Sample Report.inspx

Unit #5 (Continued)

Windows: Wood ,Fixed 8. Acceptable

Electrical: 110 VAC - No Electricity. 9. Not Inspected

10. Not Inspected **HVAC Source: Wall Unit**

11. Not Inspected

Kitchen

Open to Living Room Kitchen -

Cooking Appliances: Magic Chef 12. Not Inspected

13. Not Inspected Ventilator: Unknown 14. Not Inspected Disposal: Badger

15. Not Inspected Dishwasher: Not Applicable

16. Air Gap Present? No



Trash Compactor: Not Applicable 17. Not Inspected

18. Not Inspected Refrigerator: 19. Not Inspected Microwave:

20. Acceptable Sink: Porcelain Coated

21. Needs Attention Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



Multi Unit-Sample Report.inspx

Unit #5 (Continued)

22. Acceptable Plumbing/Fixtures: Metal/PVC23. Needs Attention Counter Tops: Formica - Eroded



24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Shelves
Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors:30. Not Inspected Windows:

31. Not Inspected HVAC Source: Wall Unit

Hallwavs

32. Acceptable33. Acceptable34. Acceptable35. Ceiling: Popcorn Closet: Shelves36. Floor: Laminate

35. Not Inspected

36. Not Inspected Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Hallway Bathroom -

38. Not Inspected

39. Acceptable Ceiling: Paint and Paneling40. Acceptable Walls: Paint and paneling

41. Acceptable42. Acceptable43. Not InspectedFloor: LaminateDoors: WoodWindows:

44. Not Inspected Electrical: 110 VAC GFCI



Multi Unit-Sample Report.inspx

Unit #5 (Continued)

45. Acceptable

46. Acceptable

47. Acceptable

48. Serviceable

Counter/Cabinet: Tile and Wood

Sink/Basin: Porcelain coated Faucets/Traps: Metal / PVC

Tub/Surround: Tile and Tile - Sewer back up or other draining issue.

Remedy immediately for health and sanitation reasons.



49. Acceptable

Shower/Surround: Tile and Tile

50. Not Inspected

Spa Tub/Surround: Toilets: Koehler

51. Acceptable

52. Not Inspected **HVAC Source:**

53. Not Inspected

Ventilation: Electric ventilation fan

Bedrooms

Rear Bedroom

54. Acceptable Closet: Large 55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable Floor: Laminate 58. Acceptable Doors: Wood

59. Acceptable Windows: Aluminum slider

60. Not Inspected Electrical: 110 VAC 61. Not Inspected **HVAC Source:**

62. Not Inspected

Balconv



Multi Unit-Sample Report.inspx

Unit #5 (Continued)

63. Acceptable Balcony Floor

Balcony Floors: Laminate - Worn out. Resurface and paint as

necessary.



64. Acceptable 65. Acceptable

Balcony Ceilings: Stucco Balcony Walls: Wood

66. Not Inspected

Balcony Electrical & Safety Railings:

Unit #6

- 1. Unit #: 26 Second floor Unit Type: Studio
- 2. Occupied

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: None4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Serviceable Floor: Carpet - Carpet Stained/soiled

7. Acceptable Doors: Wood, Aluminum Slider8. Acceptable Windows: Aluminum Fixed



Multi Unit-Sample Report.inspx

Unit #6 (Continued)

9. Serviceable Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



10. Acceptable

HVAC Source: Wall Unit

11. Acceptable

Smoke Detector: not part of this inspection.

Kitchen

Open to Living Room Kitchen -

12. Acceptable Cooking Appliances: Amana, Premier

13. Acceptable Ventilator: No Vent14. Acceptable Disposal: In-Sinkerator

15. Acceptable Dishwasher: Not applicable

16. Air Gap Present? No

17. Acceptable Trash Compactor: None18. Acceptable Refrigerator: Frigidaire

19. Acceptable Microwave: none

20. Acceptable Sink: Porcelain Coated

21. Serviceable Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled

outlet. Consult a qualified Electrician.





Multi Unit-Sample Report.inspx

Unit #6 (Continued)

22. Acceptable

Plumbing/Fixtures: Chrome /Brass

23. Acceptable

Counter Tops: Formica

24. Serviceable

Cabinets: Wood - No drawer stoppers.





25. Acceptable

26. Acceptable

27. Acceptable

28. Acceptable

29. Acceptable

30. Acceptable

31. Acceptable

Pantry: Shelves above

Ceiling: Paint and Paneling Walls: Paint and paneling

Floor: Vinyl floor covering

Doors: None

Windows: Steel Crank **HVAC Source: None**

Hallways

32. Acceptable

33. Serviceable

Ceiling: Popcorn

Closet: double door slider - Repairs needed at bypass closet doors





34. Serviceable

Floor: Carpet - Carpet Stained/soiled



Multi Unit-Sample Report.inspx

Unit #6 (Continued)

35. Acceptable Smoke Detector: Inoperative or missing.

36. Acceptable Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

right side center Bathroom -

38. Acceptable Closet: None

39. Needs Attention Ceiling: Paint and Paneling - Evidence of past or present water damage noted. To determine the existence or activity of mold,

inspection by mold expert is required.



40. Acceptable

Walls: Paint and paneling - Past repairs



41. Acceptable

42. Acceptable 43. Acceptable

Floor: Ceramic tile

Doors: Wood Windows: None



Multi Unit-Sample Report.inspx

Unit #6 (Continued)

44. Serviceable

Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



45. Acceptable Counter/Cabinet: Tile and Wood
46. Acceptable Sink/Basin: Porcelain coated
47. Acceptable Faucets/Traps: Metal / Metal

48. Acceptable Tub/Surround: Porcelain tub and ceramic tile surround

49. Acceptable Shower/Surround: Tile and Tile

50. Acceptable Spa Tub/Surround: none

51. Acceptable Toilets: Koehler, 1 1/2 Gallon Tank

52. Acceptable HVAC Source: None

53. Acceptable Ventilation:

Bedrooms

Bedroom

Balcony

54. Acceptable Balcony Floors: Concrete.55. Acceptable Balcony Ceilings: Stucco

56. Needs Attention Balcony Walls: stucco - May not be up to standards of safety, here in other balconies in this building. California height standard: 42 Inches. Safety and liability notation.



Multi Unit-Sample Report.inspx

Unit #6 (Continued)

Balcony Walls: (continued)



57. Acceptable

Balcony Electrical & Safety Railings:

Unit #7

- 1. Unit #: Number 15 first floor Unit Type: 1 bedroom
- 2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable4. Acceptable5. AcceptableCloset: NoneCeiling: PopcornWalls: Panel

6. Needs Attention Floor: Carpet - Carpet Stained/soiled

7. Acceptable
8. Acceptable
9. Not Inspected
10. Acceptable
Doors: aluminum slider
Windows: Aluminum Fixed
Electrical: None - Power off
HVAC Source: Wall Unit

11. Acceptable Smoke Detector: Inoperative or missing.

Kitchen

Open to Living Room Kitchen -



Multi Unit-Sample Report.inspx

Unit #7 (Continued)

12. Serviceable Cooking Appliances: stove - No anti tip installed



13. Not Inspected

Ventilator: Fan to Shaft - Fan inoperative



14. Acceptable Disposal: In-Sinkerator - Inoperative

15. Acceptable Dishwasher: Not applicable

16. Air Gap Present? No

17. Acceptable Trash Compactor: None

18. Acceptable Refrigerator: Whirlpool - Inoperative19. Acceptable Microwave: Danby - Inoperative

20. Acceptable Sink: Porcelain Coated

21. Acceptable Electrical: None - Not in service22. Acceptable Plumbing/Fixtures: Chrome /Brass

23. Acceptable Counter Tops: Formica



Multi Unit-Sample Report.inspx

Unit #7 (Continued)

24. Acceptable Cabinets: Wood - No drawer stoppers, here and in other units.



25. Acceptable Pantry: Single small26. Acceptable Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Needs Attention Floor: Linoleum, Carpet - Carpet Stained/soiled, here and in other

units. For sanitary reasons, replace or clean.



29. Acceptable Doors: None

30. Acceptable Windows: Aluminum slider

31. Acceptable HVAC Source: None

Hallways

32. Acceptable Ceiling: Popcorn33. Acceptable Closet: Double door

34. Floor: Carpet

35. Acceptable Smoke Detector: Inoperative or missing.



Multi Unit-Sample Report.inspx

Unit #7 (Continued)

36. Acceptable Thermostat: Inoperative



37. Acceptable

Walls: Paint and paneling

Bathrooms

Right front Bathroom

38. Acceptable Closet: None

39. Acceptable Ceiling: Paint and Paneling

40. Needs Attention Walls: Paint and paneling - Evidence of past repair or damage.



41. Needs Attention Floor: Tile - Grout missing. One or more.





Multi Unit-Sample Report.inspx

Unit #7 (Continued)

42. Acceptable

43. Acceptable

44. Serviceable

Doors: Wood Windows: None

Electrical: No GFCI or GFCI outlets. 1, Non-GFCI or GFCI labeled

outlet. Consult a qualified Electrician.2, Old outlet is due for

replacement.



45. Serviceable

Counter/Cabinet: Tile and Wood - Needs caulking



46. Acceptable

47. Acceptable

48. Serviceable

Sink/Basin: Molded single bowl Faucets/Traps: Metal / Metal

Tub/Surround: Porcelain tub and ceramic tile surround - Due for

Re-Caulking. One or more.



Multi Unit-Sample Report.inspx

Unit #7 (Continued)

Tub/Surround: (continued)





49. Acceptable

Shower/Surround: Tile and Tile

50. Acceptable

Spa Tub/Surround: None

51. Acceptable

Toilets: Toto

52. Acceptable

HVAC Source: None

53. Acceptable

Ventilation: Electric ventilation fan

Bedrooms

Rear Bedroom

54. Acceptable


55. Acceptable

56. Acceptable

Closet: double bifold

Ceiling: Popcorn

Walls: Paint and paneling



57. Acceptable

Floor: Carpet Doors: Wood

58. Acceptable 59. Acceptable

Windows: Aluminum slider

60. Needs Attention Electrical: 110 VAC - Power off

61. Acceptable

HVAC Source: None

62. Serviceable

Smoke Detector: Inoperative or missing. Inoperative, or missing. One



Multi Unit-Sample Report.inspx

Unit #7 (Continued)

Smoke Detector: (continued)

or more.

Balcony

63. Acceptable Balcony Floors: Concrete.
64. Acceptable Balcony Ceilings: Stucco

65. Serviceable Balcony Walls: stucco - Not up to safety standards, here and in other

balconies.



66. Acceptable

Balcony Electrical & Safety Railings: Power off

Unit #8

1. Unit #: 20 Unit Type: Single

2. Vacant

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: Not applicable4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable Doors: Wood, Also entry8. Acceptable Windows: Aluminum slider

9. Acceptable Electrical: 110 VAC

10. Acceptable HVAC Source: Wall Unit

11. Not Inspected Smoke Detector: Not a part of this inspection



Multi Unit-Sample Report.inspx

Unit #8 (Continued)

Kitchen

Open to Living Room Kitchen

12. Serviceable Cooking Appliances: No anti tip bracket

13. Acceptable Ventilator:

14. Serviceable Disposal: In-Sinkerator - Inoperative



15. Not Inspected Dishwasher: Not applicable

16. Air Gap Present? No

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable

20. Acceptable Sink: Porcelain

21. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



22. Acceptable Plumbing/Fixtures: Chrome /Brass

23. Acceptable Counter Tops: Formica



Multi Unit-Sample Report.inspx

Unit #8 (Continued)

24. Needs Attention Cabinets: Wood - Damaged



25. Acceptable Pantry: Small

26. Acceptable Ceiling: Paint and Paneling27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors: Not applicable30. Acceptable Windows: Aluminum crank

31. Not Inspected HVAC Source: Not applicable

Hallways

32. Acceptable Ceiling: Popcorn - Asbestos Presence Possibility: Popcorn ceiling in

this and other rooms and units, need attention as they MAY contain

asbestos. Asbestos is not harmful if it is not air born. This is a precautionary note. True test of asbestos existence is through a

certified laboratory.

33. Acceptable Closet: Large, Shelves

34. Acceptable Floor: Laminate

35. Not Inspected Smoke Detector: Not applicable

36. Acceptable Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Right side, Center Bathroom -

38. Not Inspected Closet: Not applicable

39. Acceptable Ceiling: Paint and Paneling 40. Acceptable Walls: Paint and paneling

41. Acceptable Floor: Laminate



Multi Unit-Sample Report.inspx

Unit #8 (Continued)

42. Serviceable

Doors: Wood - Loose or missing hardware



43. Not Inspected

Windows: Not applicable

44. Serviceable

Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



45. Acceptable

46. Acceptable

47. Acceptable

48. Acceptable

49. Serviceable

Counter/Cabinet: Tile and Wood Sink/Basin: Porcelain coated

Faucets/Traps: Metal / Metal

Tub/Surround: Porcelain tub and ceramic tile surround

Shower/Surround: Porcelain pan and ceramic tile surround - Cracked

tiles present



Multi Unit-Sample Report.inspx

Unit #8 (Continued)

Shower/Surround: (continued)



50. Not Inspected

Spa Tub/Surround: Not applicable

51. Acceptable

Toilets:

52. Not Inspected

HVAC Source: Not applicable

53. Acceptable

Ventilation: Electric ventilation fan

Bedrooms

Bedroom ·

Balcony

54. Acceptable
55. Acceptable
56. Acceptable
Balcony Floors: Laminate
Balcony Ceilings: Stucco
Balcony Walls: stucco

57. Not Inspected Balcony Electrical & Safety Railings: Not applicable

Unit #9

1. Unit #: 21 Unit Type: 1 bedroom

2. Occupied

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: Not applicable4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable Doors: Aluminum slider



Multi Unit-Sample Report.inspx

Unit #9 (Continued)

Windows: Aluminum Fixed, Wood casement 8. Acceptable

9. Acceptable Electrical: 110 VAC **HVAC Source: Wall Unit**

10. Acceptable

11. Not Inspected Smoke Detector: Not applicable

Kitchen

Open to Living Room Kitchen -

Cooking Appliances: No anti tip bracket 12. Serviceable

13. Acceptable Ventilator:

Disposal: Loud 14. Serviceable



Dishwasher: Not applicable 15. Not Inspected

16. Air Gap Present? No

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Acceptable Microwave:

20. Acceptable Sink: Porcelain Coated

21. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.





Multi Unit-Sample Report.inspx

Unit #9 (Continued)

22. Acceptable Plumbing/Fixtures: PVC, Chrome /Brass

23. Acceptable Counter Tops: Formica

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Single
Ceiling: Popcorn

27. Acceptable
28. Acceptable
29. Not Inspected
30. Acceptable
Walls: Paint and paneling
Floor: Vinyl floor covering
Doors: Not applicable
Windows: Aluminum crank

30. Acceptable Windows: Aluminum crank31. Not Inspected HVAC Source: Not applicable

Hallways

32. Acceptable33. Acceptable34. AcceptableFloor: Laminate

35. Not Inspected Smoke Detector: Not a part of this inspection


36. Not Inspected Thermostat: Not applicable37. Acceptable Walls: Paint and paneling

Bathrooms

Right side, Front Bathroom -

38. Not Inspected Closet: Not applicable

39. Serviceable Ceiling: Paint and Paneling - Evidence of past repair



40. Acceptable Walls: Paint and paneling41. Acceptable Floor: Vinyl floor covering

42. Acceptable Doors: Wood

43. Not Inspected Windows: Not applicable



Multi Unit-Sample Report.inspx

Unit #9 (Continued)

44. Serviceable

Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



45. Acceptable
46. Acceptable
47. Acceptable
48. Acceptable
49. Counter/Cabinet: Tile and Wood Sink/Basin: Porcelain coated Faucets/Traps: Metal / Metal
49. Acceptable
40. Acceptable
41. Acceptable
42. Acceptable
43. Acceptable
44. Acceptable
45. Acceptable
46. Acceptable
47. Acceptable
48. Acceptable
49. Acceptable
40. Acceptable
40. Acceptable
41. Acceptable
42. Acceptable
43. Acceptable
44. Acceptable
45. Acceptable
46. Acceptable
47. Acceptable
48. Acceptable
49. Acceptable
40. Acceptable<

48. Acceptable Tub/Surround: Porcelain tub and ceramic tile surround 49. Acceptable Shower/Surround: Porcelain pan and ceramic tile surround

50. Not Inspected Spa Tub/Surround: Not applicable

51. Acceptable Toilets:

52. Not Inspected HVAC Source: Not applicable53. Acceptable Ventilation: Electric ventilation fan

Bedrooms

Right side, Center Bedroom -

54. Acceptable Closet: Large, Shelves

55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable Floor: Laminate58. Acceptable Doors: Wood

59. Acceptable Windows: Aluminum crank

60. Acceptable Electrical: 110 VAC

61. Not Inspected HVAC Source: Not applicable

62. Not Inspected Smoke Detector: Not a part of this inspection

Balcony



Multi Unit-Sample Report.inspx

Unit #10

- 1. Unit #: 22, 2nd Floor Unit Type: Single-Studio
- 2. Vacant

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: None4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Not Inspected Doors:

8. Acceptable Windows: Aluminum Swing

9. Not Inspected Electrical: 110 VAC - No Electricity

10. Not Inspected HVAC Source:

11. Not Inspected

Kitchen

Open to Living Room Kitchen -

12. Acceptable

Cooking Appliances: True



13. Not Inspected Ventilator:

14. Not Inspected Disposal: Not Installed

15. Not Inspected Dishwasher:

16. Air Gap Present? No

17. Not Inspected Trash Compactor:

18. Not Inspected Refrigerator:19. Not Inspected Microwave:

20. Acceptable21. Not InspectedSink: Stainless SteelElectrical: 110 VAC



Multi Unit-Sample Report.inspx

Unit #10 (Continued)

22. Acceptable Plumbing/Fixtures: Metal/PVC

23. Acceptable Counter Tops: Formica

24. Acceptable Cabinets: Wood

25. Not Inspected

26. Acceptable Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors:30. Not Inspected Windows:

31. Not Inspected HVAC Source:

Hallways

32. Acceptable, Not Inspected Ceiling: Popcorn

33. Not Inspected Closet:

34. Acceptable Floor: Laminate

35. Not Inspected

36. Not Inspected Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Living Space Bathroom -

38. Not Inspected

39. Acceptable Ceiling: Paint and Paneling40. Acceptable Walls: Paint and paneling

41. Acceptable Floor: Laminate

42. Serviceable Doors: Wood - Lockset(s) not latching-requires adjustment

43. Not Inspected Windows:

44. Not Inspected Electrical: 110 VAC - Non-GFCI or GFCI labeled outlet. Consult a

qualified Electrician.



Multi Unit-Sample Report.inspx

Unit #10 (Continued)

Electrical: (continued)



45. Acceptable Counter/Cabinet: Composite and wood 46. Needs Attention Sink/Basin: Corian - Slow Draining



47. Acceptable

Faucets/Traps: Metal / PVC

48. Not Inspected

Shower/Surround: Tile and Glass

50. Not Inspected

Spa Tub/Surround:

51. Acceptable

49. Acceptable

Toilets:

52. Not Inspected

HVAC Source: Wall mount Electrical heat

53. Not Inspected Ventilation: Electric ventilation fan

Tub/Surround:

Bedrooms

Bedroom ·

Balcony



Multi Unit-Sample Report.inspx

Unit #11

1. Unit #: 23, 2nd floor Unit Type: Single

2. Occupied

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet:

4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable7. AcceptableFloor: Carpet Doors: Wood

8. Needs Attention Windows: Aluminum Swing, Fixed Wood,, Aluminum slider - Glasses

not tempered for safety.



9. Acceptable

Electrical: 110 VAC

10. Acceptable

HVAC Source: Wall Unit

11. Not Inspected

Kitchen

Kitchen -

12. Acceptable Cooking Appliances: Premier

13. Acceptable Ventilator: Unknown

14. Acceptable Disposal:15. Not Inspected Dishwasher:

16. Air Gap Present? No

17. Not Inspected Trash Compactor:



Multi Unit-Sample Report.inspx

Unit #11 (Continued)

18. Not Inspected Refrigerator:19. Not Inspected Microwave:

20. Acceptable Sink: Porcelain Coated

21. Needs Attention Electrical: Non-GFCI or GFCI labeled outlet.



22. Acceptable Plumbing/Fixtures: PVC,Metal

23. Acceptable Counter Tops: Laminate and composite materials

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Single small
Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling28. Acceptable Floor: Vinyl floor covering

29. Not Inspected Doors:

30. Acceptable Windows: Aluminum Swing

31. Not Inspected HVAC Source:

Hallways

32. Acceptable Ceiling: Popcorn
33. Acceptable Closet: Single small

34. Acceptable Floor: Carpet

35. Not Inspected

36. Not Inspected Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Bathroom -

38. Not Inspected

39. Acceptable Ceiling: Paint and Paneling40. Acceptable Walls: Paint and paneling



Multi Unit-Sample Report.inspx

Unit #11 (Continued)

41. Acceptable Floor: Vinyl floor covering

42. Acceptable Doors: Wood43. Not Inspected Windows:

44. Acceptable Electrical: 110 VAC GFCI45. Acceptable Counter/Cabinet: Tile

46. Acceptable
47. Acceptable
48. Acceptable
49. Acceptable
Sink/Basin: Porcelain coated
Faucets/Traps: Metal / PVC
Tub/Surround: Tile and Tile
Shower/Surround: Tile and Tile

50. Not Inspected Spa Tub/Surround:

51. Acceptable Toilets:

52. Not Inspected HVAC Source:

53. Needs Attention Ventilation: Electric ventilation fan - Semi functional and noisy

Bedrooms

Rear Bedroom

54. Acceptable Closet: Large, Shelve

55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable Floor: Carpet58. Acceptable Doors: Wood

59. Acceptable Windows: Aluminum Swing

60. Acceptable Electrical: 110 VAC 61. Not Inspected HVAC Source:

62. Not Inspected

Balcony

63. Acceptable Bal

Balcony Floors: Wood







Multi Unit-Sample Report.inspx

Unit #11 (Continued)

64. Acceptable Balcony Ceilings: Stucco Balcony Walls: stucco

66. Not Inspected Balcony Electrical & Safety Railings:

Unit #12

1. Unit #: Unit 16 Unit Type:

2. Needs Attention Note: No access. Could not inspect.

3. Vacant

Interior Rooms

Living Space -

Kitchen

Hallways

Bathrooms

Bathroom

Bedrooms

Bedroom -

Balcony

Unit #13

1. Unit #: 25, 2nd Floor Unit Type: Single-Studio

2. Vacant

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: None4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate



Multi Unit-Sample Report.inspx

Unit #13 (Continued)

7. Acceptable Doors: Wood

8. Serviceable Windows: Aluminum Swing - Missing screen, here or in other units.



Electrical: 110 VAC

HVAC Source:

9. Acceptable

10. Not Inspected

11. Not Inspected

Kitchen

Rear Left Kitchen

12. Not Inspected Cooking Appliances:

13. Acceptable Ventilator: Window

14. Not Inspected Disposal:15. Not Inspected Dishwasher:

16. Air Gap Present? No

17. Not Inspected Trash Compactor:

18. Not Inspected Refrigerator:19. Not Inspected Microwave:

20. Acceptable Sink:

21. Acceptable Electrical:

22. Acceptable23. AcceptableCounter Tops:

23. Acceptable Counter Top24. Not Inspected Cabinets:

25. Not Inspected

26. Acceptable Ceiling: Paint and Paneling

27. Acceptable Walls: Paint and tile28. Acceptable Floor: Laminate

29. Acceptable Doors:

30. Acceptable Windows: Aluminum Swing



Multi Unit-Sample Report.inspx

Unit #13 (Continued)

31. Not Inspected HVAC Source:

Hallways

32. Acceptable33. Acceptable34. AcceptableFloor: Laminate

35. Not Inspected

36. Not Inspected Thermostat:

37. Acceptable Walls: Paint and paneling

Bathrooms

Hall Way Bathroom

38. Not Inspected

39. Acceptable Ceiling: Paint and Paneling40. Acceptable Walls: Paint and paneling

41. Acceptable Floor: Vinyl floor covering, Laminate

42. Acceptable Doors: Wood43. Not Inspected Windows:44. Not Inspected Electrical:

45. Acceptable Counter/Cabinet: Tile

46. Acceptable Sink/Basin: Porcelain coated 47. Serviceable Faucets/Traps: Not Installed



48. Acceptable Tub/Surround: Tile and Tile 49. Acceptable Shower/Surround: Tile and Tile

50. Not Inspected Spa Tub/Surround:



Multi Unit-Sample Report.inspx

Unit #13 (Continued)

51. Serviceable

Toilets: Not Installed



52. Not Inspected

HVAC Source:

53. Not Inspected

Ventilation:

Bedrooms

Bedroom -

54. Not Inspected Closet:

55. Not Inspected Ceiling:

56. Not Inspected Walls:

57. Not Inspected Floor:

58. Not Inspected Doors:

59. Not Inspected Windows:

60. Not Inspected Electrical:

61. Not Inspected HVAC Source:

62. Not Inspected

Balcony

Unit #14

- 1. Unit #: Unit 24 Unit Type:
- 2. Needs Attention No access to this unit.

Interior Rooms

Living Space -

Kitchen



Multi Unit-Sample Report.inspx

Unit #14 (Continued)

Hallways

Bathrooms

Bedrooms

Bedroom

Balcony

Unit #15

- 1. Unit #: 27 Unit Type: One bedroom
- 2. Vacant

Interior Rooms

Living Room Living Space

3. Not Inspected Closet: Not applicable4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable Doors: Aluminum slider8. Acceptable Windows: Aluminum Fixed

9. Not inspected Electrical: 110 VAC - No electricity

10. Not Inspected HVAC Source: Wall Unit - No electricity

11. Not Inspected Smoke Detector: Not applicable

Kitchen

Open to Living Room Kitchen -

12. Serviceable Cooking Appliances: Amana - No anti tip is installed

13. Not Inspected Ventilator: No electricity14. Not Inspected Disposal: Not applicable

15. Not Inspected Dishwasher: No electricity

16. Air Gap Present? Yes

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable



21 Serviceable

City Property Inspections

Multi Unit-Sample Report.inspx

Unit #15 (Continued)

20. Acceptable Sink: Stainless Steel

Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



22. Acceptable Plumbing/Fixtures: PVC, Chrome /Brass

23. Acceptable Counter Tops: Formica

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Small
Ceiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors: Not applicable
 30. Acceptable Windows: Aluminum crank
 31. Not Inspected HVAC Source: Not applicable

Hallways

32. Acceptable33. Acceptable34. AcceptableFloor: Laminate

35. Not Inspected Smoke Detector: Not a part of this inspection

36. Not Inspected Thermostat: Not applicable37. Acceptable Walls: Paint and paneling

Bathrooms

Right side, Front Bathroom -

38. Not Inspected Closet: Not applicable

39. Acceptable Ceiling: Paint and Paneling 40. Acceptable Walls: Paint and paneling

41. Acceptable Floor: Laminate



Multi Unit-Sample Report.inspx

Unit #15 (Continued)

42. Acceptable Doors: Wood

43. Not Inspected Windows: Not applicable

44. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



45. Acceptable Counter/Cabinet: Granite and Wood.

46. Acceptable Sink/Basin: Porcelain coated 47. Acceptable Faucets/Traps: Metal / PVC

48. Acceptable Tub/Surround: Porcelain tub and ceramic tile surround 49. Acceptable Shower/Surround: Porcelain pan and ceramic tile surround

50. Not Inspected Spa Tub/Surround: Not applicable

51. Acceptable Toilets:

52. Not Inspected HVAC Source: Wall Unit - No electricity

53. Not Inspected Ventilation: No electricity

Bedrooms

Right side, Rear Bedroom -

54. Acceptable Closet: Large55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable58. AcceptableDoors: Wood

59. Acceptable Windows: Aluminum crank

60. Not Inspected Electrical: 110 VAC - No electricity 61. Not Inspected HVAC Source: Not applicable

62. Not Inspected Smoke Detector: Not a part of this inspection

Balcony

63. Acceptable Balcony Floors: Wood



Multi Unit-Sample Report.inspx

Unit #15 (Continued)

64. Acceptable Balcony Ceilings: Stucco Balcony Walls: stucco

66. Not Inspected Balcony Electrical & Safety Railings: Not applicable

Unit #16

1. Unit #: 28 Unit Type: Single

2. Vacant

Interior Rooms

Living Room Living Space -

3. Acceptable4. AcceptableCloset: LargeCeiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Laminate

7. Acceptable Doors: Wood, Also entry8. Acceptable Windows: Aluminum crank

9. Not Inspected Electrical: 110 VAC - No electricity
 10. Not Inspected HVAC Source: Wall Unit - No electricity

11. Not Inspected Smoke Detector: Not a part of this inspection

Kitchen

Open to Living Room Kitchen ·

12. Not Inspected Cooking Appliances: No electricity

13. Not Inspected
14. Not Inspected
15. Not Inspected
16. Disposal: Not applicable
17. Disposal: Not applicable
18. Not Inspected
19. Dishwasher: Not applicable

16. Air Gap Present? No

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable

20. Acceptable Sink: Stainless Steel

21. Not Inspected Electrical: None

22. Acceptable Plumbing/Fixtures: PVC, Chrome

23. Acceptable Counter Tops: Formica

24. Acceptable Cabinets: Wood



Multi Unit-Sample Report.inspx

Unit #16 (Continued)

25. Acceptable26. AcceptableCeiling: Popcorn

27. Acceptable Walls: Paint and paneling

28. Acceptable Floor: Laminate

29. Not Inspected Doors: Not applicable30. Not Inspected Windows: Not applicable

31. Not Inspected HVAC Source: Not applicable

Hallways

Bathrooms

Right side, Front Bathroom

32. Not Inspected Closet: Not applicable

33. Acceptable Ceiling: Paint and Paneling34. Acceptable Walls: Paint and paneling

35. Acceptable Floor: Laminate 36. Acceptable Doors: Wood

37. Not Inspected Windows: Not applicable

38. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



39. Not Inspected Counter/Cabinet:

40. Acceptable Sink/Basin: Porcelain coated
41. Acceptable Faucets/Traps: Metal / PVC
42. Not Inspected Tub/Surround: Not applicable
43. Acceptable Shower/Surround: Tile and Tile
44. Not Inspected Spa Tub/Surround: Not applicable

45. Acceptable Toilets:

46. Not Inspected HVAC Source: Wall Unit - No electricity



Multi Unit-Sample Report.inspx

Unit #16 (Continued)

47. Not Inspected Ventilation: Electric ventilation fan - No electricity

Bedrooms

Balcony

Unit #17

1. Unit #: 29 Unit Type: One bedroom

2. Occupied

Interior Rooms

Living Room Living Space -

3. Not Inspected Closet: Not applicable

4. Acceptable Ceiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Carpet

7. Acceptable Doors: Aluminum slider8. Acceptable Windows: Aluminum Fixed

9. Acceptable Electrical: 110 VAC

10. Acceptable HVAC Source: Wall Unit

11. Not Inspected Smoke Detector: Not applicable

Kitchen

Open to Living Room Kitchen -

12. Serviceable Cooking Appliances: No anti tip is installed

13. Acceptable Ventilator:14. Acceptable Disposal:

15. Not Inspected Dishwasher: Not applicable

16. Air Gap Present? No

17. Not Inspected Trash Compactor:

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable

20. Acceptable Sink: Porcelain



Multi Unit-Sample Report.inspx

Unit #17 (Continued)

21. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



22. Acceptable Plumbing/Fixtures: PVC, Chrome

23. Acceptable Counter Tops: Formica

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Single
Ceiling: Popcorn

27. Acceptable
28. Acceptable
29. Not Inspected
30. Acceptable
31. Not Inspected
Walls: Paint and paneling
Floor: Vinyl floor covering
Doors: Not applicable
Windows: Aluminum crank
HVAC Source: Not applicable

Hallways

32. Acceptable33. Acceptable34. AcceptableFloor: Carpet

35. Not Inspected Smoke Detector: Not a part of this inspection

36. Not Inspected Thermostat: Not applicable 37. Acceptable Walls: Paint and paneling

Bathrooms

Left side, Front Bathroom -

38. Not Inspected Closet: Not applicable

39. Needs Attention Ceiling: Paint and Paneling - Evidence of past or present water

staining.

40. Needs Attention Walls: Paint and paneling - Past water damage noted.

41. Acceptable Floor: Vinyl floor covering



Multi Unit-Sample Report.inspx

Unit #17 (Continued)

42. Acceptable Doors: Wood

43. Not Inspected Windows: Not applicable

44. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



45. Acceptable Counter/Cabinet: Tile and Wood
46. Acceptable Sink/Basin: Porcelain coated
47. Acceptable Faucets/Traps: Metal / Metal

48. Acceptable Tub/Surround: Porcelain tub and ceramic tile surround49. Acceptable Shower/Surround: Porcelain pan and ceramic tile surround

50. Not Inspected Spa Tub/Surround: Not applicable

51. Acceptable Toilets:

52. Not Inspected HVAC Source: Not applicable53. Acceptable Ventilation: Electric ventilation fan

Bedrooms

Left side, Rear Bedroom -

54. Acceptable Closet: Large55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable58. AcceptableDoors: Wood

59. Acceptable Windows: Aluminum crank

60. Acceptable Electrical: 110 VAC

61. Not Inspected HVAC Source: Not applicable

62. Not Inspected Smoke Detector: Not a part of this inspection

Balcony

63. Acceptable Balcony Floors: Wood



Multi Unit-Sample Report.inspx

Unit #17 (Continued)

64. Acceptable Balcony Ceilings: Stucco Balcony Walls: stucco

66. Not Inspected Balcony Electrical & Safety Railings: Not applicable

Unit #18

1. Unit #: 30 Unit Type: One bedroom

2. Vacant

Interior Rooms

Living Room Living Space -

3. Not Inspected4. AcceptableCloset: Not applicableCeiling: Popcorn

5. Acceptable Walls: Paint and paneling

6. Acceptable Floor: Carpet

7. Serviceable Doors: Aluminum slider - Loose or missing hardware



8. Acceptable Windows: Aluminum Fixed

9. Not Inspected Electrical: 110 VAC - No electricity

10. Not Inspected HVAC Source: Wall Unit - No electricity

11. Not Inspected Smoke Detector: Not a part of this inspection

Kitchen

Open to Living Room Kitchen

12. Serviceable Cooking Appliances: No anti tip is installed

13. Not Inspected Ventilator: Power off14. Not Inspected Disposal: In-Sinkerator



Multi Unit-Sample Report.inspx

Unit #18 (Continued)

15. Not Inspected Dishwasher: Not applicable

16. Air Gap Present? No

17. Not Inspected Trash Compactor: Not applicable

18. Not Inspected Refrigerator: Not a part of this inspection

19. Not Inspected Microwave: Not applicable

20. Acceptable Sink: fiberglass

21. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



22. Acceptable Plumbing/Fixtures: PVC, Chrome

23. Acceptable Counter Tops: Formica

24. Acceptable
25. Acceptable
26. Acceptable
Cabinets: Wood
Pantry: Small
Ceiling: Popcorn

27. Acceptable
28. Acceptable
29. Not Inspected
30. Acceptable
31. Not Inspected
Walls: Paint and paneling
Floor: Vinyl floor covering
Doors: Not applicable
Windows: Aluminum crank
HVAC Source: Not applicable

Hallways

32. Acceptable Ceiling: Popcorn - Asbestos Presence Possibility: Popcorn ceiling in

this and other rooms need attention as they MAY contain asbestos. Asbestos is not harmful if it is not air born. This is a precautionary note. True test of asbestos existence is through a certified laboratory.

33. Acceptable Closet: Shelves34. Acceptable Floor: Carpet

35. Not Inspected Smoke Detector: Not a part of this inspection



Multi Unit-Sample Report.inspx

Unit #18 (Continued)

36. Not Inspected Thermostat: Not applicable37. Acceptable Walls: Paint and paneling

Bathrooms

Left side, Front Bathroom -

38. Not Inspected Closet: Not applicable

39. Acceptable
40. Acceptable
41. Acceptable
Floor: Vinyl floor covering

42. Acceptable Doors: Wood

43. Not Inspected Windows: Not applicable

44. Serviceable Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified

Electrician.



45. Acceptable Counter/Cabinet: Tile and Wood
46. Acceptable Sink/Basin: Molded dual bowl
47. Acceptable Faucets/Traps: Metal / Metal

48. Serviceable Tub/Surround: Due for Re-Caulking



49. Acceptable Shower/Surround: Porcelain pan and ceramic tile surround



Multi Unit-Sample Report.inspx

Unit #18 (Continued)

50. Not Inspected Spa Tub/Surround: Not applicable

51. Acceptable Toilets:

52. Not Inspected HVAC Source: Not applicable

53. Not Inspected Ventilation: Electric ventilation fan - No electricity

Bedrooms

Left side, Rear Bedroom -

54. Acceptable Closet: Large55. Acceptable Ceiling: Popcorn

56. Acceptable Walls: Paint and paneling

57. Acceptable Floor: Carpet58. Acceptable Doors: Wood

59. Acceptable Windows: Aluminum crank

60. Not Inspected Electrical: 110 VAC

61. Not Inspected HVAC Source: Not applicable

62. Not Inspected Smoke Detector: Not a part of this inspection

Balcony

63. Acceptable
64. Acceptable
65. Acceptable
Balcony Floors: Wood
Balcony Ceilings: Stucco
Balcony Walls: stucco

66. Not Inspected Balcony Electrical & Safety Railings: Not applicable

Unit #19

- 1. Unit #: Unit 31 Unit Type:
- 2. Needs Attention Note: This unit was not inspected due to COVID-19

Interior Rooms

Living Space

Kitchen

Hallways

Bathrooms



Multi Unit-Sample Report.inspx

Unit #19 (Continued)

Bathroom ·

Bedrooms

Bedroom -

Balcony

Unit #20

- 1. Unit #: Unit 32, 3rd floor Unit Type: Studio
- 2. Occupied

Interior Rooms

Living Room Living Space ·

3. Serviceable Closet: Doors are hard to operate.





4. Acceptable
5. Acceptable
6. Acceptable
7. Acceptable
Ceiling: Walls: Floor: Doors:



Multi Unit-Sample Report.inspx

Unit #20 (Continued)

8. Serviceable

Windows: Alumimun - Hard operation. Lubricate, repair or replace as necessary.



Kitchen

Rear Kitchen

9. Serviceable

Cooking Appliances:



10. Serviceable

Ventilator: No ventilator hood and ducting installed. For sanitation and health reasons, recommend installation





Multi Unit-Sample Report.inspx

Unit #20 (Continued)

11. Acceptable Disposal:

12. Not Inspected Dishwasher: Not installed.

13. Not Inspected14. Not Inspected15. Not Inspected16. Not Inspected17. Not Inspected18. Not Inspected19. Not In

16. Acceptable Sink: Porcelain

17. Serviceable Electrical: Two socket outlet without ground. Recommend

replacement.



18. Acceptable Plumbing/Fixtures:

19. Acceptable Counter Tops: Formica

20. Acceptable Cabinets:

21. Not Inspected
22. Acceptable
23. Acceptable
Walls: Paint and paneling

24. Acceptable Floor: Vinyl25. Acceptable Doors: Wood

26. Acceptable Windows: Alumimun, Crank

27. Not Inspected HVAC Source:

Hallways

28. Acceptable Ceiling: Popcorn

29. Not Inspected Closet: Not Applicable

30. Acceptable Floor: Carpet

31. Not Inspected

32. Acceptable Thermostat:

33. Acceptable Walls: Paint and paneling

Bathrooms



Multi Unit-Sample Report.inspx

Unit #20 (Continued)

Rear Bathroom

34. Not Inspected

35. Acceptable Ceiling: Paint and Paneling 36. Acceptable Walls: Paint and paneling

37. Acceptable Floor: 38. Acceptable Doors:

39. Not Inspected Windows: Not Applicable

40. Serviceable Electrical: 1. Non GFCI outlet, 2. Two socket outlet without ground.

Recommend replacement.





41. Acceptable42. Acceptable43. Acceptable5ink/Basin:Faucets/Traps:Tub/Surround:

44. Not Inspected Shower/Surround: Not Applicable 45. Not Inspected Spa Tub/Surround: Not Applicable

46. Serviceable Toilets: The toilet is loose



47. Acceptable

Bedrooms

Ventilation: Electric ventilation fan



Multi Unit-Sample Report.inspx

Unit #20 (Continued)

Bedroom

Balcony

48. Needs Attention Balcony Floors: Scupper drain is stuffed with debris and it needs cleaning, to prevent water back up into the unit.





49. Acceptable 50. Acceptable

51. Acceptable

Balcony Walls:

Balcony Ceilings:

Balcony Electrical & Safety Railings:



Multi Unit-Sample Report.inspx

Cost Estimate Summary

Items Recommended for Rplace	<u>Materials</u>	<u>Labor</u>
Lots and Grounds		
Fences:	\$ 3000	\$ 7000
Exterior	•	·
Exterior Surface Type: Repair and painting of the exterior	\$ 3000	\$ 8000
Windows:	\$ 1800	\$ 7000
Structure	φ 1000	φ / 000
Stairs/Handrails:	\$ 1000	\$ 3000
Roof	ψ 1000	ψ 3000
Main Structure Roof Surface Material: To revitalize the		\$ 20000
		φ 20000
roof deck by a professional roofer.		
Electrical		Ф 420000
Electrical System: Rough estimate of parts and material		\$ 130000
estimate, not including permits and wall restorations		
after destruction.		
Plumbing		^
Water Lines:		\$ 7000
Utility room and Mall space (between pool deck and rear		
units) Water Heater Water Heater Operation:		\$ 600
Heating System		
Thermostats: Rough estimate of repairs.		\$ 4500
<u>Unit #7</u>		
Open to Living Room Kitchen Cabinets: Cost of repairs for		\$ 3500
all units		
Open to Living Room Kitchen Floor: Cost of Cleaning for		\$ 3500
all units.		
Balcony Walls: Cost of addition of rails for safety for all		\$ 8000
units balconies.		,
Unit #13		
Living Room Living Space Windows:		\$ 1200
Rplace Total	\$ 8800	\$ 203300
Total	Ψ 3000	Ψ – 00000



Multi Unit-Sample Report.inspx

Cost Estimate Summary (Continued)

Repair Total

Cost Estimate Total \$ 212100



Multi Unit-Sample Report.inspx

Needs Attention Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

- 1. Walkways: Safety Notation: Any area or spot with level or grade differential, projected objects from ground, openings on walk path and notable unevenness inside or outside the property should be repaired or improved to prevent trip and injury hazard. If improvement is not desired or not possible, use with caution and use night lighting. Photos could be sample representative, as all areas may not have been visible or accessible to the inspector.
- 2. Retaining Walls: Minor cracks and separation noted. Monitor and maintain.
- 3. Parking Lot: Monitor and maintain per following reasons:
 - 1. Crack on floor without displacement, 2. Moisture affects, efflorescence (salty residue due to moisture seepage) on concrete ceilings is evident and minor concrete chipping are evident.

Exterior

- 4. Exterior Surface Type: Stucco 1.Any opening, separation, or crack on the exterior walls should be sealed patched and painted as necessary, to prevent further decay and admittance of water, insect or rodent traffic, 2. Entire exterior is due for resurfacing and paint coating
- 5. Windows: Some of the window security bars are not equipped with release mechanism from inside, for emergency existing.

Structure

6. Bearing Walls: Minor cracks noted. Monitor and maintain.

Roof

7. Plumbing Vents: 1. Many are due for replacement, 2. Some are covered with asbestos.

Unit #1

- 8. Living Room Living Space Windows: Aluminum Fixed Not Tempered glasses
- 9. Open to Living Room Kitchen Dishwasher: SPT Needs to fit in right.
- 10. Rear Bedroom Closet: Large Closet door needs repair. Tracks / Guides / Wheels are missing or not functional.



Multi Unit-Sample Report.inspx

Needs Attention Summary (Continued)

Unit #5

- 11. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 12. Open to Living Room Kitchen Counter Tops: Formica Eroded

Unit #6

- 13. right side center Bathroom Ceiling: Paint and Paneling Evidence of past or present water damage noted. To determine the existence or activity of mold, inspection by mold expert is required.
- 14. Balcony Walls: stucco May not be up to standards of safety, here in other balconies in this building. California height standard: 42 Inches. Safety and liability notation.

Unit #7

- 15. Living Room Living Space Floor: Carpet Carpet Stained/soiled
- 16. Open to Living Room Kitchen Floor: Linoleum, Carpet Carpet Stained/soiled, here and in other units. For sanitary reasons, replace or clean.
- 17. Right front Bathroom Walls: Paint and paneling Evidence of past repair or damage.
- 18. Right front Bathroom Floor: Tile Grout missing. One or more.
- 19. Rear Bedroom Electrical: 110 VAC Power off

Unit #8

20. Open to Living Room Kitchen Cabinets: Wood - Damaged

Unit #10

21. Living Space Bathroom Sink/Basin: Corian - Slow Draining

Unit #11

- 22. Living Room Living Space Windows: Aluminum Swing, Fixed Wood,, Aluminum slider Glasses not tempered for safety.
- 23. Kitchen Electrical: Non-GFCI or GFCI labeled outlet.
- 24. Bathroom Ventilation: Electric ventilation fan Semi functional and noisy

Unit #12

25. Note: No access. Could not inspect.



Multi Unit-Sample Report.inspx

Needs Attention Summary (Continued)

Unit #14

26. No access to this unit.

Unit #17

- 27. Left side, Front Bathroom Ceiling: Paint and Paneling Evidence of past or present water staining.
- 28. Left side, Front Bathroom Walls: Paint and paneling Past water damage noted.

Unit #19

29. Note: This unit was not inspected due to COVID-19

Unit #20

30. Balcony Floors: Scupper drain is stuffed with debris and it needs cleaning, to prevent water back up into the unit.



Multi Unit-Sample Report.inspx

Serviceable Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. Fences: Fence at right side (protective barrier for pool deck) is aged and due for replcement.

Exterior

- 2. Trim: Wood Due for repair and painting.
- 3. Fascia: Wood Due for repair and painting.
- 4. Exterior Lighting: Exposed wiring at different areas noted. Cover and secure as possible. Consult an electrician.

Structure

5. Stairs/Handrails: 1. Safety hazard with sharp top, 2. Short for protection, 3. Openings / Spacing at Balusters / Frame bars: Too far apart. Child and pet safety. Recommend installing more obstruction for safety.

Roof

- 6. Main Structure Roof Surface Material: 1.Minor sporadic repair / patching needed at present, 2. Water ponding stains evident. Monitor and maintain, 3. Roof material has been covered with gravel at a few areas that show sagging. This is an improper way of draining water, and moisture entrapment under the gravel will reduce the life expectancy of the area covered, 4. Per notations in 3, the sagging of the roof deck must be corrected as a long term remedy for proper draining, as this roof is not equipped with scupper system and it is slope draining system. Consult a roofer.
- 7. Flashing: Water pregnable
- 8. Gutters: Gutters should be corrected in pitch, not to become stuffed.

Electrical

- 9. Electrical System: Due to all notations below and other deficiencies, such 2 socket and Non GFCI, age of system, possible lack of safety and proper grounding and exposed wiring, total revitalization of the electrical system, for safety and liability reasons, is recommended.
- 10. Left Side Electric Panel Manufacturer: Federal Pacific 1.Federal Pacific panel breakers, with "Stab Lock" design have a history of not tripping when circuit overloading occurs. Consult a qualified electrician to verify if replacement is needed, 2.



Multi Unit-Sample Report.inspx

Serviceable Summary (Continued)

11. Emergency Lighting: Not installed. Consult an electrician.

Plumbing

- 12. Water Lines: 1.At rear: Between pool rear retaining wall and front units rear parameter walls-, A. One or more copper-galvanized connections are of improper fitting material which may cause "Dielectric" or Galvanic / Electrolysis, leading to rupture. Consult a plumber for remedy and cost, B. Corrosion on galvanized pipe can cause rupture at any time 2. In Sub Garage: Swere and other drain lines show corrosion, and past leakage signs, which are susceptible to leakage at any time. Recommend repair / replacement by a professional plumber, to prevent damaged on vehicles parked underside the said pipes, as well as health and sanitation issues. Some temporary repairs by felt rapping noted.
- 13. Drain Pipes: See above notes.
- 14. Utility room and Mall space (between pool deck and rear units) Water Heater Water Heater Operation: Functional at time of inspection Some routine maintenance on boiler and reserve tank are needed. Consult a plumber.

Heating System

15. Thermostats: Some of the thermostats and Wall units are not functional.

Unit #1

- 16. Open to Living Room Kitchen Electrical: Non GFCI outlet
- 17. Hall Way Bathroom Electrical: Non GFCI outlet

Unit #2

- 18. Living Room Living Space Ceiling: Paint and Paneling Evidence of past or present water staining. Invasive inspection will reveal plumbing leakage or roof water pregnable points.
- 19. Living Room Living Space Walls: Paint and paneling Evidence of past or present water damage noted. To determine the existence or activity of mold, inspection by mold expert is required.
- 20. Open to Living Room Kitchen Cooking Appliances: No anti tip is installed (Comes with the new unit from manufacturer). Anti tip is a bracket that holds the unit from tipping in case the front door is opened and weight is applied on it or a person (child) stands on the door. It secures the Oven Range to the wall or floor. This was tested simply by pulling back on the unit. A safety notation.



Multi Unit-Sample Report.inspx

Serviceable Summary (Continued)

- 21. Open to Living Room Kitchen Ventilator: Fan inoperative
- 22. Open to Living Room Kitchen Disposal: In-Sinkerator Inoperative
- 23. Open to Living Room Kitchen Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 24. Open to Living Room Kitchen Walls: Paint and paneling Evidence of past or present water damage noted. To determine the existence or activity of mold, inspection by mold expert is required.
- 25. Left side, Rear Bathroom Walls: Paint and paneling Evidence of past or present water damage noted. To determine the existence or activity of mold, inspection by mold expert is required.

Unit #3

- 26. Right side rear Kitchen Ventilator: No Vent Microwave in operative.
- 27. Right side rear Kitchen Microwave: No name Inoperative
- 28. Right side rear Kitchen Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician. One or more.
- 29. Thermostat: Inoperative,
- 30. Front left Bathroom Electrical: 110 VAC Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician. One or more.
- 31. Front left Bathroom Tub/Surround: Porcelain tub and ceramic tile surround Cracked tiles. One or more.
- 32. Rear Bedroom Windows: Aluminum slider Handle missing.
- 33. Balcony Floors: Concrete. Monitor and maintain. Negative ptich and water ponding.

 Unit #4

34. Living Room Living Space Ceiling: Popcorn - Water stains noted. Holes for water release noted. Invasive inspection may reveal possible mold presence.

- 35. Living Room Living Space Walls: Paint and paneling Loose or peeling paint.
- 36. Living Room Living Space Floor: Laminate Floor; stained.
- 37. Living Room Living Space Electrical: not in service Not in service.
- 38. Living Room Living Space Smoke Detector: Inoperative or missing. Inoperative, or missing. One or more.
- 39. left rear Kitchen Plumbing/Fixtures: Chrome /Brass Water leakage.
- 40. left rear Kitchen Cabinets: Wood No drawer stops. One or more
- 41. Ceiling: Popcorn Stress cracks



Multi Unit-Sample Report.inspx

Serviceable Summary (Continued)

- 42. Thermostat: Inoperative
- 43. left side center Bathroom Electrical: 110 VAC Power off
- 44. left side center Bathroom Counter/Cabinet: Tile and Wood Sliding door; Will not open. One or more.

Unit #5

45. Hallway Bathroom Tub/Surround: Tile and Tile - Sewer back up or other draining issue. Remedy immediately for health and sanitation reasons.

Unit #6

- 46. Living Room Living Space Floor: Carpet Carpet Stained/soiled
- 47. Living Room Living Space Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 48. Open to Living Room Kitchen Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 49. Open to Living Room Kitchen Cabinets: Wood No drawer stoppers.
- 50. Closet: double door slider Repairs needed at bypass closet doors
- 51. Floor: Carpet Carpet Stained/soiled
- 52. right side center Bathroom Electrical: No GFCI or GFCI outlets. Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.

Unit #7

- 53. Open to Living Room Kitchen Cooking Appliances: stove No anti tip installed
- 54. Right front Bathroom Electrical: No GFCI or GFCI outlets. 1, Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.2, Old outlet is due for replacement.
- 55. Right front Bathroom Counter/Cabinet: Tile and Wood Needs caulking
- 56. Right front Bathroom Tub/Surround: Porcelain tub and ceramic tile surround Due for Re-Caulking. One or more.
- 57. Rear Bedroom Smoke Detector: Inoperative or missing. Inoperative, or missing. One or more.
- 58. Balcony Walls: stucco Not up to safety standards, here and in other balconies.

Unit #8

- 59. Open to Living Room Kitchen Cooking Appliances: No anti tip bracket
- 60. Open to Living Room Kitchen Disposal: In-Sinkerator Inoperative
- 61. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



Multi Unit-Sample Report.inspx

Serviceable Summary (Continued)

- 62. Right side, Center Bathroom Doors: Wood Loose or missing hardware
- 63. Right side, Center Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 64. Right side, Center Bathroom Shower/Surround: Porcelain pan and ceramic tile surround Cracked tiles present

Unit #9

- 65. Open to Living Room Kitchen Cooking Appliances: No anti tip bracket
- 66. Open to Living Room Kitchen Disposal: Loud
- 67. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 68. Right side, Front Bathroom Ceiling: Paint and Paneling Evidence of past repair
- 69. Right side, Front Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.

Unit #10

- 70. Living Space Bathroom Doors: Wood Lockset(s) not latching-requires adjustment Unit #13
- 71. Living Room Living Space Windows: Aluminum Swing Missing screen, here or in other units.
- 72. Hall Way Bathroom Faucets/Traps: Not Installed
- 73. Hall Way Bathroom Toilets: Not Installed

Unit #15

- 74. Open to Living Room Kitchen Cooking Appliances: Amana No anti tip is installed
- 75. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 76. Right side, Front Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.

Unit #16

77. Right side, Front Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.



Multi Unit-Sample Report.inspx

Serviceable Summary (Continued)

Unit #17

- 78. Open to Living Room Kitchen Cooking Appliances: No anti tip is installed
- 79. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 80. Left side, Front Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.

Unit #18

- 81. Living Room Living Space Doors: Aluminum slider Loose or missing hardware
- 82. Open to Living Room Kitchen Cooking Appliances: No anti tip is installed
- 83. Open to Living Room Kitchen Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 84. Left side, Front Bathroom Electrical: Non-GFCI or GFCI labeled outlet. Consult a qualified Electrician.
- 85. Left side, Front Bathroom Tub/Surround: Due for Re-Caulking

Unit #20

- 86. Living Room Living Space Closet: Doors are hard to operate.
- 87. Living Room Living Space Windows: Alumimun Hard operation. Lubricate, repair or replace as necessary.
- 88. Rear Kitchen Cooking Appliances:
- 89. Rear Kitchen Ventilator: No ventilator hood and ducting installed. For sanitation and health reasons, recommend installation
- 90. Rear Kitchen Electrical: Two socket outlet without ground. Recommend replacement.
- 91. Rear Bathroom Electrical: 1. Non GFCI outlet, 2. Two socket outlet without ground. Recommend replacement.
- 92. Rear Bathroom Toilets: The toilet is loose